

From: ["Stuesse, Gregory L." <stuessegl@cdmsmith.com>](mailto:stuessegl@cdmsmith.com)
To: ["Sheldrake, Sean" <sheldrake.sean@epa.gov>](mailto:sheldrake.sean@epa.gov)
["Zhen, Davis" <Zhen.Davis@epa.gov>](mailto:Zhen.Davis@epa.gov)
CC: ["Scott Coffey" <coffeyse@cdmsmith.com>](mailto:coffeyse@cdmsmith.com)
["lrby-Smith, Karen" <lrbySmithKE@cdmsmith.com>](mailto:lrbySmithKE@cdmsmith.com)
Date: 5/24/2018 11:48:02 AM
Subject: Surface Sediment Photos from the Tieton 5/24
Attachments: [SG-B330_2018_05_24 \(1\).JPG](#)
[SG-B330_2018_05_24 \(2\).JPG](#)
[SG-B330_2018_05_24 \(3\).JPG](#)

Sean and Davis -

Attached are photos from Karen on the Tieton that is sampling today at Stratified Random Sample locations. Photos were taken at SG-B330 located near RM 9.5 to 10 at mid-channel. The crew performed 5 attempts within a 25 ft radius, the 1st grab with 250 lb weights over-penetrated the sediments and 100 lb were removed. Grab 2 was empty, grabs 3 through 4 with 150 lbs attached recovered greater than 30 cm and grab 5 recovered 32 cm with no weights. The 3 samples were composited for a 3-point composite sample.

The crew plans on sampling on the west side of the river between RM 9 and 11 this afternoon.

Thanks, Greg

Greg Stuesse, PE, LG | Senior Project Manager | CDM Smith

14432 SE Eastgate Way, Suite 100 | Bellevue, WA 98007

Main: 425.519.8300 | Direct: 425.519.8358 | Cell: 206-715-6752

stuessegl@cdmsmith.com | <mailto:stuessegl@cdmsmith.com%7C> www.cdmsmith.com <<http://www.cdmsmith.com>>